

## **Monday, May 8, 2017**

As I have previously shared, during the weekend of April 8, 2017 a plumbing failure occurred, resulting in flooding of the Related Arts wing and front office area at LKMS. HCPSS Facilities and outside contractors have worked very hard to clean up and repair any collateral damage that occurred.

During the process of carpet replacement on May 5, 2017, a small amount of mold growth was discovered on the drywall behind a large storage cabinet that was moved for carpet replacement.

The damaged drywall was removed and replaced on Saturday, May 6, 2017.

If you have any questions, please contact Mrs. Lublin or Mrs. Ober.