

Tuesday, April 25, 2017

Building Update/IEQ Notice

As I have previously shared, during the weekend of April 8, 2017 a plumbing failure occurred, resulting in flooding of the Related Arts wing and front office area at LKMS. HCPSS Facilities and outside contractors have worked very hard to clean up and repair any collateral damage that occurred.

During the process of inventory of damaged items, a small amount of mold growth was discovered on some of the damaged sheet-music books and instruments (cello, chimes and violin) located in the Orchestra storage room. This room experienced the majority of the overhead water flow directly from the damaged pipe above over an extended period of time.

The damaged books and instruments were bagged and removed from the school.

If you have any questions, please contact Mrs. Lublin or Mrs. Ober.

Thank you,

Lucy D. Lublin, Principal